

Windows 10 and USB connection with GNSS device


This guide will describe how to establish USB connection with the following:

- SXBlue GNSS receiver or other GNSS devices
- Computer running under Windows 10

Step 1 : Device Manager

Connect your GNSS device with the USB cable to your computer. Usually Windows 10 doesn't require any driver for this device connection.

From the **Device Manager** page of Windows 10, you should see a not fully detected device under **Other Devices** marked with yellow triangle.



Step 2 : Pairing Device

Point your device and right click with the mouse.

On the pup up menu, select **Update Driver Software**

Wait until update has been completed. Some computer require to do it a second time. Some computer reboot and complete update by itself.

